

## VISUAL TANK INSPECTION REPORT

Vessel :
Port/Terminal:
Product/Cargo:

ETT-115

HERCULES/FREEPORT

N. BUTANOL

Your Reference:

Our Reference: FP/97-5105

Date : 2-18-97

T <b>ank</b> Number	1C	2C	3C	
Tank Coating	MILD STEEL	MILD STEEL	MILD STEEL	
Last Cargo	N. BUTANOL	N. BUTANOL	N. BUTANOL	
Second Last Cargo				
Cargo	<u> </u>			
/isual Cleanliness _Accepted *	ACCEPTED	ACCEPTED	ACCEPTED	
<pre>lime/Date Inspected</pre>	2-18-97 @ 1545	2-18-97 @ 1545	2-18-97 @ 1545	

tethod said to have been used to clean tanks: ALL CARGO TANKS AND PIPELINES WERE STRIPPED ONE HOUR, VENTED FOUR HOURS, AND FLOWN FOR TWO HOURS,

nformation regarding previous cargoes, tank coating and cleaning method was obtained from vessel personnel and cannot be maranteed as accurate by Caleb Brett U.S.A., Inc. and no liability can be assumed for errors resulting from improper nformation supplied. This report, of necessity, is based on such information.

The cleanliness of inspected tank(s) is/are based on visual inspection of tank surfaces and line system at accessible areas only. This document does not cover the cleanliness of tank surfaces and line system at inaccessible spots and/or possible release of components of previous cargoes during loading, discharge or transport of the cargo in question, for which the vessel is fully responsible. Suitability of tank coating for intended cargo must be guaranteed by vessel's owner or by suppliers of the coating.

I T S-Caleb Brett